

Building Renewal Grant Application

Initial Submission Date:

Application ID: 620

Resubmittal Date:

Please provide as much of the requested information as possible. SFB staff will assist in developing required information that is not currently available.

District Name: Casa Grande Elementary District

Superintendent: Dr. Frank Davidson

Contact Person: Frank Corder

Contact Phone Number: 520-251-1857

Contact Email: frank.corder@cgelem.k12.az.us

School Site: Saguaro Elementary School

Buildings:

Description of Problem

Please include a detailed description of the issues, as well as a description of and a copy of any professional studies, citations or reports from government entities, recommended solutions, and any cost information or estimates. If additional space is needed, please attach.

The SAGARO SCHOOL HAS TWO COOLING TOWERS TAT ARE THE SAME AGE. WE HAVE EXPERIENCE A CONDITION WHERE THE BLOWER WHEEL HAS DISENGAGED FROM THE BEARING ASSEMBLY AND HAS DAMAGED THE BLOWER ASSEMBLY. UPON ADDITIONAL REVIEW OF THE TOWERS, WE DISCOVERED THAT THE FOUR 4 INCH MOTORIZED BUTTERFLY VALVES ARE FROOZE UP AND THE DRIFT ELIMINATORS ARE CORRODED AND DAMAGED.

QUOTES WERE SOLICITATED FROM 3 HVAC CONTRACTORS, TWO WALK-THROUGHS WERE CONDUCTED AND TWO CONTRACTORS SUBMITTED BIDS. ATTACHED IS THE BID RESULTS IN A FORMAT THAT IDENTIFIES THE FULL SCOPE IN THE BASE BID AND 3 ALTERNATES.

I RESPECTFULLY REQUESRT FULL FUNDING OF \$19,822.80

Project Category: HVAC

Are any of the above-described issues in buildings or part of buildings that are leased to another entity, including a district sponsored charter school? N

Available Funding

Current unencumbered building renewal fund balance (Fund 690):	\$0.00
Amount of Local funds planned for this project	\$0.00

Please outline any associated insurance coverage.

Liaison: Cruse

pcruse@azsfb.gov

602-364-1193

7/9/2013 12:51:38 PM

Building Renewal Grant Application

Superintendent Printed Name

Superintendent Signature

Date